

MEMO

ATTN DAVE HAYSCH
FRM: JOHN TREZCNA
RE: TIB S1006 PROCESSORS

26/4

The following are the I/C I've found and reasoned, need replacing as a result of the 1200 CPU being plugged into memory slot

Board: 107 000033-13

U2, U3, U4, U20, U21, U24, U33, U41, U43, U45, U52, U62, U75, U76, U78, U77, U84, U85, U94.

REGARDS