

PARTS LIST  
ZETACO

FOR: EXTERNAL B CABLE ASSEMBLY

ASSEMBLY #: 300-011-00  
REV. LEVEL: F

ITEM	QTY	PART #	GENERIC DESCRIP.	DESCRIPTION	REFERENCE
----	----	-----	-----	-----	-----
1	1	026-027-00	CONN M	50 POSITION	
2	26	028-008-00	CONN PIN M	24-28 GAUGE	
3	1	030-038-00	CONN HDW	AMP 1-747098-1 HOOD	
5	1	030-017-00	CONN HDW	1-745129-7 FERRULE IN	
6	1	030-019-00	CONN HDW	1-745130-0 FERRULE OUT	
7	1	020-003-00	CABLE	SHLD 13TWP 28AWG 26CNDCT	
8	1	025-037-00	CONN F	3M 3399-6026 26S	
9	1	030-034-00	CONN HDW	3M 3490-5 PULL TAB	
10	2	099-011-00	LABEL	SLSH-20375 BRADY RND CBL	
11	1	018-020-00	CABLE MATL	1/2" THERMOFIT	
12	1	093-006-00	WIRE TERM	SPADE LUG 12-10	
13	1	018-025-00	CABLE MATL	1/4" THERMOFIT	

End of List

No Control Documents on file for this list

WIRE LIST  
ZETACO

FOR: EXTERNAL B CABLE ASSEMBLY

ASSEMBLY #: 300-011-00  
REV. LEVEL: F

WIRE NO.	GA.	COLOR	ORIGIN CONN.	PIN#	TERM METHOD	DESTINATION CONN.	PIN#	TERM METHOD	SIGNAL NAME/REMARKS
1	28	BRN	P1	1	MASS	P2	1	2	TW PR
2	28	BLK	P1	2	MASS	P2	2	2	
3	28	RED	P1	3	MASS	P2	3	2	TW PR
4	28	BLK	P1	4	MASS	P2	4	2	
5	28	ORG	P1	5	MASS	P2	5	2	TW PR
6	28	BLK	P1	6	MASS	P2	6	2	
7	28	YEL	P1	7	MASS	P2	7	2	TW PR
8	28	BLK	P1	8	MASS	P2	8	2	
9	28	GRN	P1	9	MASS	P2	9	2	TW PR
10	28	BLK	P1	10	MASS	P2	10	2	
11	28	BLU	P1	11	MASS	P2	11	2	TW PR
12	28	BLK	P1	12	MASS	P2	12	2	
13	28	VIO	P1	13	MASS	P2	13	2	TW PR
14	28	BLK	P1	14	MASS	P2	14	2	
15	28	GRY	P1	15	MASS	P2	15	2	TW PR
16	28	BLK	P1	16	MASS	P2	16	2	
17	28	WHT	P1	17	MASS	P2	17	2	TW PR
18	28	BLK	P1	18	MASS	P2	18	2	
19	28	RED	P1	19	MASS	P2	19	2	TW PR
20	28	BRN	P1	20	MASS	P2	20	2	
21	28	ORG	P1	21	MASS	P2	21	2	TW PR
22	28	BRN	P1	22	MASS	P2	22	2	
23	28	YEL	P1	23	MASS	P2	23	2	TW PR
24	28	BRN	P1	24	MASS	P2	24	2	
25	28	GRN	P1	25	MASS	P2	25	2	TW PR
26	28	BRN	P1	26	MASS	P2	26	2	