

FIELD ENGINEERING SUPPORT SOUTHBORO

*Technical Information Bulletin*

**TIB**

DATE: FEBRUARY 13, 1974  
FROM: R. JENSEN  
SUBJECT: MARGINAL I/C

NUMBER: S1006  
CATEGORY: PROC.OPTIONS  
MODEL: 8020

---

Signetics I/C P/N 8243 (DGC P/N 100 000 137) with date code 7313 has experienced approximately 25% failure rate at board test in Southboro. Other date coded 8243's do not exhibit this failure rate.

Beware that all I/C's with this date code, being part of the same lot, may have this problem. Any 8243 I/C's in stock with this date code should be replaced. Please return these parts to Southboro for possible credit from vendor.

*Done R#  
3-14-74*